




F16.2



F16.3



F16.4









FIG. 7B


30A
FILE. 8A
304
306
310
306
310



F14.8B







F16.9




FIG. 10




FIG.11




FIG. 12





FIG.13







FIG. 15



F16.16A

F16. 16B








FIG.17A


F16.17B















F(6.30

F14.29



500 500

F16. 32







FIG. 33




F14.34





Fib. 35



F16.36








Title: Optical Fiber...Coupler Assembly

806

F14. 44

808

802



F14.43




Fig. 45




Fig. 46




Fig. 47









Fig. 48













F16. 52A






8011

F16. 5







1009865 CTLSOT

tig 54